RCA CLEANING PROCEDURE (1)

RCA Cleaning request

1. In your Cmi account, select « RCA request »

RCA cleaning request

User: dbouvet

Time of request (on the server): Thu Apr 02 2020 06:56:50 UTC

RCA date: Wednesday 22.04.20 ▼

Reminder: Deadline @14:00 the working day before the RCA cleaning.

2. Select the date

Lot(s):

Account	Wafer*	Wafer ID	History* ⑦	RCA type ⑦	Thin-film requested* ⑦	Remark
Développements ▼	number / material ▼ / size ▼			full ▼		

3. Select the billing account

4. Enter the number of samples
5. Select the material of the sample
6. Select the size of the sample

RCA CLEANING PROCEDURE (2)

RCA Cleaning request

9.Select the clening type

. Full : RCA1 + HF1:10 + RCA2 + SRD

. Without HF : RCA1 + RCA2 + SRD

. Without SRD : RCA1 + HF1:10 + RCA2 + drying at air

. Without HF & SRD : RCA1 + RCA2 + drying at air

. RCA 2 only : Piranha (done by the user) + RCA2 + SRD

. Other : To be specified in "Remark"

RCA cleaning request

User: dbouvet

Time of request (on the server): Thu Apr 02 2020 06:56:50 UTC

RCA date: Wednesday 22.04.20 ▼

Reminder: Deadline @14:00 the working day before the RCA cleaning.

Lot(s):

Account	Wafer*	Wafer ID	History* ⑦	RCA type ⑦	Thin-film requested* ⑦	Remark
Développements ▼	number / material ▼ / size ▼			full ▼		

10. Enter the layer and the thickness

7. enter the wafer ID if relevant

8. enter a brief description of the last steps before cleaning

* MANDATORY

Send | Reset | Quit

11. Press « Send ». You will receive a confirmation by e.mail