

Main hazards



- Risk of gloves, loose clothing, long hair, or jewellery being caught in the rotating tool or spindle
- Propelled chips or tool splinters, injuries caused by rotating or projected workpieces
- Cuts to the hands from chips or sharp-edged workpieces



Safety rules

- Use only safe drill presses and bench drills and follow the instructions in the operating instructions.
- Use only by trained personnel. Use is prohibited for young workers under 18 years of age (exception: initial vocational training).
- Wear safety glasses.
- Wear safety shoes.
- Gloves are prohibited.
- Do not wear rings, watches, or bracelets.
- Do not wear loose clothing, especially around the sleeves.
- Long hair: wear a hairnet.
- Secure workpieces with clamping devices.
- Never put your hand near the moving spindle.
- Never clamp or loosen a workpiece while the machine is running.
- Never carry out measurements, cleaning, or repairs while the machine is running.