

Main hazards



- Fingers amputation by the blade
- Crushed fingers under the clamping device or between the sheet metal and the worktable
- Crushed fingers between fixed and moving parts
- Cuts to the hands from handling sharp-edged sheet metal
- Injuries from falling sheet metal



Safety rules

- Use safe guillotine shears and follow the instructions in the operating instructions.
- Wear cut-resistant gloves (at least protection level 3).
- Wear safety shoes.
- Wear hearing protection if necessary, e.g., when cutting thick sheet metal.
- Set the front guard as low as possible.
- Do not place your fingers under the front guard; narrow sheet metal strips must be held with tools.
- Do not place your fingers between the sheet metal and the worktable.
- Use a support when cutting long sheet metal.
- Do not stand behind the guillotine shears.